




X2




X2




X3



X1



X6



A

M10x100

X4



B

M8x12

X24



C

M8x16

X12




M10x120

X1




M8x85

X1




Ø12x1.0x120

X1




Step 1

M10x100




Step 3

M8x16



Step 2

M8x12



Step 4